




Micron filter units, replaced filters in both. Water on the floor is the source of ice under building. Water is from various leaks.



Another view of water on floor from leaks several different leaks that have been repaired.



Motorized grill and pre heat coil for dryer make up air. Temperature of air shown. Outside temp was 0 degrees F.



Air entered dryer area prior to installation of motorized grill, we blocked this air passage with plywood.



Air passage from boiler room to plant. This allowed makeup air to dryers prior to installation of motorized grill. We closed this



Window was covered with plywood, we replaced window with new one.